
CAROLINA JET



1979 Beechcraft B58 Baron N984BC / TH-984









1999 Cessna 182S N2380Y / 18280465

Aircraft / Engine / Prop

Airframe Total Time: 2733 Tach Time Hobbs Meter Since New: 3093.3

Engine Since Rebuild by Lycoming: 995 Hours (February 11, 2009) Prop Since Major Overhaul: 194 Hours (Overhauled March 2016)

Avionics

- Aspen Evolution PFD 1000 / 500
- Garmin GTN 650 GPS / Nav / Com / WAAS
- Garmin GMA 35 Audio Panel
- KMH 880 Traffic System
- King KAP-140 Autopilot
- Electric Trim
- Turn Coordinator
- Handheld Mic

- Garmin GNC 225 Nav / Com
- Garmin GTX 335 Transponder w/ ES
- Ground Proximity Warning / TAWS B
- Standby AI / DG / AS / Alt / VS
- Amp / Suction Gauge
- AOA Indicator
- Artex ELT
- Four place Headset Jacks

Equipment / Inspections

- Engine Cowl Plugs / Pitot Cover
- Sporty's Battery Charger
- Cabin Fire Extinguisher
- Windshield Sunsheild
- LED Landing Light
- Cargo Net
- Hobbs Meter
- Wheel Pants
- Plug for Battery Charger (Baggage Comp.)

- Bruce's Aircraft Cover
- Two Tow Bars
- Rosen Visors
- Checkmate 182 Checklist
- Sheepskin Seat Covers (Pilot / Copilot)
- Carbon Monoxide Detector
- JPI EDM-930 Engine Monitor
- Pitot Heat
- Annual Inspection Due Feb. 2023

Exterior

White with Blue and Gray Accent Stripes.

Interior

Gray Leather with Matching Carpet, Side-panels and Headliner.



3821 N LIBERTY ST, SUITE 200A WINSTON-SALEM, NC 27105 PHONE: 336.971.2134 BRANDON@CAROLINAJET.COM







3821 N LIBERTY ST, SUITE 200A WINSTON-SALEM, NC 27105 PHONE: 336.971.2134 BRANDON@CAROLINAJET.COM



