## CAROLINA JET



# 1978 Beechcraft B58 Baron N984BC / TH-984





### 1978 Beechcraft B58 Baron N984BC / TH-984

#### Airframe / Engines / Props

Airframe Hours Since New: 7,411

Engine Hours Since Overhaul: 200 / 200 (Overhauled by Triad Aviation April 2019)

Prop Hours Since Overhaul: 200 / 200 (Overhauled June 2019)

#### **Avionics**

• Garmin G500 TXi Flight Display

• Garmin TXi Engine Information System

• Synthetic Vision

• Dual Garmin GTN-750 Nav / Com / GPS

• Garmin GFC-600 Auto Pilot

Garmin GI-106B Nav Indicator w/ GS

• Six Place Intercom

WAAS / ADS-B In and Out

- Garmin GMA-35C Remote Audio Panel
- Garmin GDL-69 XM Weather
- Garmin GTX-345 Transponder ADS-In/Out
- Co-pilot PTT on the Panel
- L3 Comm Backup Attitude Indicator
- Electric Trim
- Second VOR Indicator with Glideslope

#### **Equipment**

- Cabin Comfort Plus Air Conditioner
- Fire Extinguisher Fuel 166 Gallons
- Rosen Sun Visors
- Pilot Cabin Door Steward
- G&D Window Inserts
- Pulse Lights
- Cup Holders

- Prop Sync
- Control Wheel Map Light
- External Power Receptacle
- Spring Thing Baggage Door Holder
- Rosen Visors
- GAMI Injectors
- Bruce's Aircraft Cover

#### **Exterior**

White with Two Tone Green Accent Stripes.

#### **Interior**

Brown Leather Seats with matching side-panels, carpet and headliner. Pilot and Copilot Seats covered in brown leather and sewn in sheepskins. Interior was refurbished April 2018.